

Intertek The Warehouse Brewery Lane Leigh WN7 2RJ UK Tel +44 1942 265 700 consumergoods.uk@intertek.com Intertek.com

## FLAMMABILITY TEST REPORT

Report No.: LEI20031541A Date Received: 12/03/20 Date Tested: 18/03/20 Date Issued: 18/03/20

Company Name & Address: VEROTEX INDUSTRIES BV

EDISONWEG 3 5466 AR VEGHEL NETHERLANDS

**Contact Name:** 

Sample Details:

Order No.:

Description:

Ref/Style No.:

Colour:

Not stated

Not stated

Not stated

Quality: XFR - Requiem
Supplier: Not stated
Batch No.: Not stated
End Use: Not stated

End Use: Not stated
Quoted Fibre Composition: Not stated
Retailer: Not stated
Specification No.: Not stated

Sample Description: Blue coloured woven fabric with white coloured backing

Test Method	Pre Treatment	Requirement	Result
BS 5852: 2006 Clause 11 (Upholstery Composite) Ignition source 5 (Crib 5)	Watersoak as Annex E of BS 5852: 2006	BS 5852: 2006 Clause 11 (Upholstery Composite) Ignition source 5 (Crib 5)	NI/5 (PASS)

The upholstered composite tested meets the performance requirements for resistance to ignition as detailed in the Medium Hazard (Crib 5 only) category of Table 1 in Clause 4 of BS 7176: 2007.

Note: The customer requested that RX36110 foam with an approximate density 35 kg/m<sup>3</sup> be used as the filling material

## Sampling and frequency of testing

Each upholstery composite shall be tested in accordance with the relevant tests identified in Table 1 for the appropriate hazard category every 2,500 units produced or once per month. Retesting shall be carried out where there is any major basic alteration to a furniture specification (e.g. of fibre content, construction, flame-retardant finish or mass per unit area of fabric, density or type of filling or change of materials manufacturer). Changes in the colour (where the fabric was flame-retardant finished in the same batch) of the product or minor changes in the pattern or construction, e.g. of the order of 2 picks/cm, shall not be deemed sufficient reason to necessitate retesting.

STEVEN OWEN ANDREW HALLETT CAROLE SPOWART GREGORY JAMES
(Technical & Operational (Flammability Team Leader) (Flammability Technician)
Excellence Manager) Administrator)

Report No.: LEI20031541A Page 1 of 2

ITS Testing Services (UK) Ltd
Registered in England No. 1408264. Registered Office: Academy Place, 1-9 Brook Street, Brentwood, Essex, CM14 5NQ









Intertek The Warehouse Brewery Lane Leigh WN7 2RJ UK Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com

## FLAMMABILITY TEST REPORT

Test Specification
Test Method:

Test Method: BS 5852:2006 Clause 11 (upholstery composite) Ignition source 5

Foam specification
Supplier / Grade: Ca

Carpenter / RX36110 (As requested by the customer) 450 x 450 x 75mm (back) & 450 x 300 x 75mm (seat)

Density / Hardness: 34-36kg/m³ /105-115N

Conditioning

Prior to Testing: At least 72 hours in ambient indoor conditions, then at least 24 hours in an atmosphere having a

temperature of 23  $\pm$  2°C and a relative humidity of 50  $\pm$  5%

At Time of Testing: Temperature of 10 °C to 30 °C and a relative humidity of 15 % to 80 %

Test Results

"The following test results relate only to the ignitability of the combination of upholstery composites (BS 5852: 2006, Clause 11) under the particular conditions of test stated; they are not intended as a means of assessing the full potential fire hazard of the materials or products in

iterion of Ignition  mouldering Criteria  ternally detectable amounts of smoke, heat or glowing  minutes after crib ignition  calating smouldering behaviour rendered the test unsafe to continue and juired forcible extinction  nouldering essentially consumed the test specimen within the duration the test / Smouldering reached the extremities of the test specimen ther than the top of the vertical part of the test specimen) within the	N N	ío ío	N	Z Zo					
nouldering Criteria  ternally detectable amounts of smoke, heat or glowing minutes after crib ignition calating smouldering behaviour rendered the test unsafe to continue and quired forcible extinction nouldering essentially consumed the test specimen within the duration the test / Smouldering reached the extremities of the test specimen	N	lo .							
ternally detectable amounts of smoke, heat or glowing minutes after crib ignition calating smouldering behaviour rendered the test unsafe to continue and quired forcible extinction nouldering essentially consumed the test specimen within the duration the test / Smouldering reached the extremities of the test specimen	N	lo .		·					
minutes after crib ignition calating smouldering behaviour rendered the test unsafe to continue and quired forcible extinction nouldering essentially consumed the test specimen within the duration the test / Smouldering reached the extremities of the test specimen	N	lo .		<del></del>					
nouldering essentially consumed the test specimen within the duration the test / Smouldering reached the extremities of the test specimen			N	lo					
the test / Smouldering reached the extremities of the test specimen	N			No					
ration of the test		0	No						
aming Failure									
the test specimen continued to flame for more than 10 minutes after the nition of the crib	No		No						
calating combustion behaviour rendered the test unsafe to continue and quired forcible extinction	No		No						
aming essentially consumed the test specimen within the duration of the	No		No						
aming reached the extremities of the test specimen (Other than the top the vertical part of the test specimen) within the duration of the test	No		No						
bris from the test specimen caused an isolated floor fire that continued flame for more than 10 minutes after the ignition of the crib	No		No						
nal Examination									
ogressive smouldering was observed when the sample was dismantled	No		No						
idence of charring within the filling (other than discolouration) more in 100mm in any direction, apart from upwards, from the nearest part of coriginal position of the ignition source	No		No						
me to extinction of flames after crib ignition	7 Minutes 35 Seconds		5 Minutes 34 Seconds						
ne to extinction of glowing after crib ignition	Due to the position of the crib within the test specimen it was not possible to see when glowing ceased		Due to the position of the crib within the test specimen it was not possible to see when glowing ceased						
ne to extinction of smoke after crib ignition	Due to the amount of smoke in the test enclosure it was not possible to see when smoking ceased		Due to the amount of smoke in the test enclosure it was not possible to see when smoking ceased						
ximum extent of damage to back (mm) Length / Width	400	103	400	97					
ximum extent of damage to base (mm) Length / Width	57	105	62	90					
st Result	NI/5 (P	PASS)		NI/5 (PASS)					
Ignitability performance index: "Clause 11 - NUS"									

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have <u>aimed</u> to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or willful misconduct.

Report No.: LEI20031541A Page 2 of 2

ITS Testing Services (UK) Ltd
Registered in England No. 1408264. Registered Office: Academy Place, 1-9 Brook Street, Brentwood, Essex, CM14 5NQ





