

Intertek The Warehouse Brewery Lane Leigh WN7 2RJ UK Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com

FLAMMABILITY TEST REPORT

Company Name & Address: VEROTEX INDUSTRIES

EDISONWEG 3 5466 AR VEGHEL NETHERLANDS

Contact Name:

Sample Details:

Order No.:

Not stated

Description: Ref/Style No.: Not stated Not stated

Colour:

Not stated

Quality: Supplier:

XFR - Labyrinth
Not stated

Batch No.:

Not stated

End Use:

Not stated

Quoted Fibre Composition:

Not stated

Retailer:

Not stated

Specification No.:

Not stated

Sample Description:

Grey coloured woven fabric with white coloured backing

| Test Method | Pre Treatment | Requirement | Result |
|---|--|-------------|--------|
| BS 5852: 2006 Clause 11 (Upholstery Composite) Ignition source 5 (Crib 5) | Watersoak as Annex E of BS 5852: 2006 | | |

The upholstered composite tested **meets** the performance requirements for resistance to ignition as detailed in the Medium Hazard (Crib 5 only) category of Table 1 in Clause 4 of BS 7176: 2007.

Note: The customer requested that RX36110 foam with an approximate density 35 kg/m³ be used as the filling material

Sampling and frequency of testing

Each upholstery composite shall be tested in accordance with the relevant tests identified in Table 1 for the appropriate hazard category every 2,500 units produced or once per month. Retesting shall be carried out where there is any major basic alteration to a furniture specification (e.g. of fibre content, construction, flame-retardant finish or mass per unit area of fabric, density or type of filling or change of materials manufacturer). Changes in the colour (where the fabric was flame-retardant finished in the same batch) of the product or minor changes in the pattern or construction, e.g. of the order of 2 picks/cm, shall not be deemed sufficient reason to necessitate retesting.

STEVEN OWEN ANDREW HALLET

ANDREW HALLETT (Flammability Team Leader)

CAROLE SPOWART
(Flammability

Administrator)

GREGORY JAMES
(Flammability Technician)

Report No.: LEI19050307A Page 1 of 2

(Technical & Operational

Excellence Manager)

ITS Testing Services (UK) Ltd
Registered in England No. 1408264. Registered Office: Academy Place, 1-9 Brook Street, Brentwood, Essex, CM14 5NQ











Intertek
The Warehouse
Brewery Lane
Leigh WN7 2RJ
UK

Tel +44 1942 265 700 consumergoods.uk@intertek.com intertek.com

FLAMMABILITY TEST REPORT

Test Specification

Test Method:

BS 5852:2006 Clause 11 (upholstery composite) Ignition source 5

Foam specification

Supplier / Grade:

Carpenter / RX36110 (As requested by the customer)

450 x 450 x 75mm (back) & 450 x 300 x 75mm (seat)

Density / Hardness: 34-36kg/m³ /105-115N

Conditioning

Prior to Testing:

At least 72 hours in ambient indoor conditions, then at least 24 hours in an atmosphere having a

temperature of 23 \pm 2°C and a relative humidity of 50 \pm 5%

At Time of Testing:

Temperature of 10 °C to 30 °C and a relative humidity of 15 % to 80 %

Test Result

"The following test results relate only to the ignitability of the combination of upholstery composites (BS 5852: 2006, Clause 11) under the particular conditions of test stated; they are not intended as a means of assessing the full potential fire hazard of the materials or products in

| Test number / position | 11_ | | 2 | | | | |
|--|---|-----|---|-----|--|--|--|
| Criterion of Ignition | | | | | | | |
| Smouldering Criteria | | | | | | | |
| Externally detectable amounts of smoke, heat or glowing | No | | No | | | | |
| 60 minutes after crib ignition | 140 | | 140 | | | | |
| Escalating smouldering behaviour rendered the test unsafe to continue and required forcible extinction | No | | No | | | | |
| Smouldering essentially consumed the test specimen within the duration of the test / Smouldering reached the extremities of the test specimen (Other than the top of the vertical part of the test specimen) within the duration of the test | No | | No | | | | |
| Flaming Fallure | | | | | | | |
| The test specimen continued to flame for more than 10 minutes after the ignition of the crib | No | | No | | | | |
| Escalating combustion behaviour rendered the test unsafe to continue and required forcible extinction | No | | No | | | | |
| Flaming essentially consumed the test specimen within the duration of the test | No | | No , | | | | |
| Flaming reached the extremities of the test specimen (Other than the top of the vertical part of the test specimen) within the duration of the test | No | | No | | | | |
| Debris from the test specimen caused an isolated floor fire that continued to flame for more than 10 minutes after the ignition of the crib | No | | No | | | | |
| Final Examination | | | | | | | |
| Progressive smouldering was observed when the sample was dismantled | No | | No | | | | |
| Evidence of charring within the filling (other than discolouration) more than 100mm in any direction, apart from upwards, from the nearest part of the original position of the ignition source | No | | No | | | | |
| Time to extinction of flames after crib ignition | 5 Minutes 29 Seconds | | 5 Minutes 43 Seconds | | | | |
| Time to extinction of glowing after crib ignition | 7 Minutes 31 Second | | 8 Minutes 17 Seconds | | | | |
| Time to extinction of smoke after crib ignition | Due to the amount of smoke in the test enclosure it was not possible to see when smoking ceased | | Due to the amount of smoke in the test enclosure it was not possible to see when smoking ceased | | | | |
| Maximum extent of damage to back (mm) Length / Width | 400 | 128 | 400 | 142 | | | |
| Maximum extent of damage to base (mm) Length / Width | 88 | 130 | 79 | 122 | | | |
| Test Result | NI/5 (PASS) | | NI/5 (PASS) | | | | |
| Ignitability performance index: "Clause 11 - NI/5" | | | | | | | |

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or willful misconduct.

Report No.: LEI19050307A Page 2 of 2









